




As your reliable partner for remanufacture, replacement as well as repair and maintenance of drive shafts, we are **now also able to offer** main drive shafts for the new model A 907 MB Sprinter in OE quality as a new part for your replacement needs.

THE PART NUMBERS BELOW ARE AVAILABLE OFF-THE-SHELF:



OHP-No.	DB-No.	Type	Lz [mm]
315449	A9074106000	TH-1	3476
315450	A9074106100	TH-2	3478,5
315451	A9074106300	TH-2	3417
315452	A9074106400	TH-1	3447
315453	A9074106500	TH-2	3449,5
315454	A9074106700	TH-2	3388
315455	A9074107700	TW-1	2813
315456	A9074101401	TW-4	2789,5
315457	A9074101501	TW-4	2757
315458	A9074101601	TW-4	2729,5



We are looking forward to your enquiries. Please contact us. Your Uni-Cardan® Team.
E-Mail: customerservice.duesseldorf@walterscheid.com | Phone: 0800 – 165 65 00